

Triple B Home Inspection, LLC

TRUST A PROFESSIONAL
Professional Radon Testing Department

Date: 01/01/12

Client: Mr. & Mrs. Joe Homeowner

Test Address: 1234 First St.
Wisconsin

Test Location: Basement

Radon Testing Equipment Information:

PROFESSIONAL CONTINUOUS RADON MONITOR

Model Number: 1027

Serial Number: 64302047-2010-02

Manufactured by Sun Nuclear Corp.
425A Pineda Court

Melbourne, Florida 32940-7508

<http://www.sunnuclear.com>

RESULTS:

Test Start: **01/01/2012/2910 @ 4:00 PM**

Test Stop: **01/04/2012 @ 10:00 AM**

Radon Level: 17.0 pCi/L

Corrective action recommended: **YES**

The results indicate that the testing device registered **at or above** the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends fixing your home if the results taken in the lowest level of the home suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (EPA Document #402-K-03-002, Revised February 2003) or contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon

6.7	14.0	17.2	9.6	10.8	15.6	15.2	17.2	11.2
11.6	18.5	16.1	15.2	15.6	11.2	9.2	12.8	14.0
23.3	18.5	18.5	11.2	17.6	16.5	14.0	11.2	9.2
17.2	14.0	16.8	17.2	13.2	17.2	12.5	13.6	16.5
21.7	17.6	20.5	20.5	18.8	23.7	13.2	18.1	19.7
22.1	25.0	17.6	26.5	17.6	21.7	18.5	21.7	T 17.2
17.2	14.8	11.2	24.5	25.3	21.7			
14.5	14.0	15.2	21.7	16.8	15.6			

Overall Avg.=16.7

EPA Protocol Avg.=17.0

Procedures used to conduct this radon test comply with all United States Environmental Protection Agency's (EPA) recommendations.

Test performed by : Tim Wendorff

TRIPLE B HOME INSPECTION, LLC

(262)-224-4420

www.triplebhi.com

Triple B Home Inspection, LLC and employees do not assume responsibility or liability, collectively and individually, for any financial or health consequences of subsequent action or lack of action taken by the customer or it's consultants based on Triple B Home Inspection-provided results.